



### Input/Output XLR

Pin 1:Ground

Pin 2:Hot

Pin 3:Cold



12V/5W

### Lamp out

Pin 1:Chassis


Pin 2:n.c

Pin 3:Ground

Pin 4:+ 12V

### Tape IN/OUT

R IN L



R OUT L



### Insert

Tip: Send

Ring: Return

Sleeve: Ground




Input/Output

Tip: Hot

Ring: Cold

Sleeve: Ground

### POWER SUPPLY OUTPUT SOCKET



PIN1: + 17V

PIN2: - 17V

PIN3: GROUND

PIN4: + 48V

PIN5: SHIELD

PIN6: SWITCH OUTPUT RELAYS