


SOFTWARE SUPPORT


WINDOWS 8

Installing unsigned drivers in Windows 8

- 1 Press and hold  +  to launch the charm bar.
- 2 Hold the  button (Shift) and restart the computer.




- 3 Choose "Troubleshoot".



4 Click on "Advanced options".



5 Choose "Startup Settings".




6 Now press "Restart".



7 Upon startup you will be given a bunch of options to choose from.

Press **7** on your keyboard to boot into Windows 8 with the driver signature check disabled.



8 During installation, you are advised that the driver is not safe.

Press: "Install this driver software anyway".

