




2x Sub



8x Top



6x Sub



WIRING
Input:
1 +/- = MF +/-
2 +/- = HF +/-
Link:
1 +/- = MF +/-
2 +/- = HF +/-



Loudspeaker Management



WIRING

Input:
1 +/- = Sub +/-
2 +/- = n.c.
Link:
1 +/- = Sub +/-
2 +/- = n.c.